









ATTACHMENT C PHOTOLOG SITE PHOTOGRAPHS TRUIMPH EXPLOSIVES INCORPORATED FUDS PROPERTY NUMBER C03MD1012




Photo 7: Panoramic View of the rest of the Herron Farm from the north along Zeitler Road looking southeast.




Photo 9: View of munitions constituents (MC) and debris in the area of the former "Firehole".



Photo 11: View looking north of the southeastern portion of the former Firehole area. MC debris was noted in the plowed fields.



Photo 8: Panoramic View of the rest of the Herron Farm from the north along Zeitler Road looking south.



Photo 10: View looking north of the former Firehole area. MC debris was noted in the planted fields.



Photo 12: View looking southeast of the Thiokol Motor Recovery Area (TMRA). Note the debris in the Background.



ATTACHMENT C PHOTOLOG SITE PHOTOGRAPHS TRUIMPH EXPLOSIVES INCORPORATED FUDS PROPERTY NUMBER C03MD1012



Photo 1: View of the northern boundary of the former firehole. Zeitler Road is beyond the plowed field.




Photo 3: Panoramic View (1 of 2) Firehole Area from the north along Zeitler Road looking southwest.




Photo 5: Panoramic View of the rest of the Herron Farm from the north along Zeitler Road looking south/southeast.



Photo 2: Additional view of the northern boundary of the former firehole. Zeitler Road is beyond the plowed field.



Photo 4: Panoramic View (2 of 2) Firehole Area from the north along Zeitler Road looking south.






Photo 6: Panoramic View of the rest of the Herron Farm from the north along Zeitler Road looking south/southeast.



















TEIZrarm6.MDI


ElZtarm7.MD1













rm3.MD1



